

Dependent Resurvey of the Subdivisional
Lines, T. 33 N., R. 33 E., M.D.M., Nevada

CHAINS		
80.17	<p>Set a steel fence post, 5-1/2 ft. long, alongside the iron post.</p> <p>The cor. of secs. 1, 6, 7 and 12 on the West bdy. of the township.</p>	
40.09	<p>From the cor. of secs. 5, 6, 7 and 8.</p> <p>N. 0° 18' E., bet. secs. 5 and 6.</p> <p>Over nearly level land, through medium growth of shadscale and budsage.</p> <p>Point for the 1/4 sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original cor.</p> <p>Set an iron post, 28 ins. long, 2-1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 33 N R 33 E 1/4 S 6 S 5 1974</p>	
79.70	<p>Set a steel fence post, 5-1/2 ft. long, alongside the iron post.</p> <p>Wash, 10 lks. wide, 1 ft. deep, drains N. 75° W.</p>	
79.98	<p>The cor. of secs. 5, 6, 31 and 32 on the North bdy. of the township.</p>	
<p>Completion of the Dyer Survey, T. 33 N., R. 33 E., M.D.M., Nevada</p>		
22.90	<p>From the cor. of secs. 23, 24, 25 and 26, heretofore described.</p> <p>North, bet. secs. 23 and 24.</p> <p>Over nearly level land, through medium growth of shadscale and budsage.</p> <p>Wash, 20 lks. wide, 2 ft. deep, drains S. 40° E.</p>	
30.00	<p>No evidence of the monument established by Dyer in 1864, not monumented.</p>	
40.00	<p>Point for the 1/4 sec. cor. of secs. 23 and 24.</p> <p>Set an iron post, 28 ins. long, 2-1/2 ins. diam., 16 ins. in the ground and in a collar of stone, with brass cap mkd.</p> <p style="text-align: center;">T 33 N R 33 E 1/4 S 23 S 24 1974</p> <p>Set a steel fence post, 5-1/2 ft. long, alongside the iron post.</p>	