

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
T. 20 N., R. 30 E., MDM, NEVADA

CHAINS
40.23

Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 33, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with aluminum cap mkd.

T20N R30E
S 33
 $\frac{1}{4}$ S 4
T19N

1979

set a steel fence post, $5\frac{1}{2}$ ft. long, alongside the aluminum post.

60.345 Point for the W $\frac{1}{16}$ sec. cor. of secs. 4 and 33.

Set an aluminum post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with aluminum cap mkd.

W $\frac{1}{16}$ S 33
S 4

1979

set a steel fence post, $5\frac{1}{2}$ ft. long, alongside the aluminum post.

80.46 The cor. of secs. 4, 5, 32 and 33, monumented with a basalt stone, 16x10x6 ins., firmly set 10 ins. in the ground, mkd. with 2 grooves on W. face and 4 grooves on E. face.

At the corner point

Set an aluminum post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with aluminum cap mkd.

T20N R30E
S 32 | S 33
S 5 | S 4
T19N

1978

bury the original cornerstone and set a steel fence post, $5\frac{1}{2}$ ft. long, alongside the aluminum post.

DEPENDENT RESURVEY OF A PORTION
OF THE SUBDIVISIONAL LINES,
T. 20 N., R. 30 E., MOUNT DIABLO MERIDIAN, NEVADA

Reestablishment of the Survey Executed by
E.B. Monroe, U.S. Deputy Surveyor,
in 1868.