

DEPENDENT RESURVEY OF M.S. NO. 37, CHAMPION LODGE

CHAINS

Reset the original wooden post alongside the aluminum post.

Thence S. $86^{\circ} 52'$ E.

0.764

Intersect the line between secs. 33 and 34, at a point from which:

The cor. of secs. 27, 28, 33 and 34, hereinbefore described, bears N. $1^{\circ} 15'$ W., 12.866 chs. dist.

6.026

Cor. No. 1, M.S. No. 37, Champion Lode and the place of beginning.

GENERAL DESCRIPTION

The land within Township 16 North, Range 64 East is about 7,100 to 10,300 ft. above sea level and is mountainous land. The soil is rocky. The land is covered with sagebrush, buckbrush, pinon pine, juniper, aspen, mahogany, bristlecone pine and native grass.

The township is drained by Mosier, Tamberlaine, Bone Yard and Sagehen Canyons.

Springs are located in secs. 1 and 14. Tamberlaine Spring is located in sec. 35.

Principal users of the area are sheepmen and cattlemen.

Excavations indicating search for minerals are located throughout the area.