

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
T. 34 N., R. 55 E., MDM, NEVADA

<p>CHAINS 40.78</p>	<p>The cor. of secs. 5, 6, 31 and 32, monumented with a wooden post, 4 ins. square, 4 ft. long, loosely set in a mound of earth with a steel fence post, 5½ ft. long, firmly set alongside. This corner was found by R. W. Millard, Registered Land Surveyor, and is shown on the plat of "Meadow Valley Ranchos Unit No. 9," as approved by the Board of County Commissioners of Elko County on Sept. 8, 1966.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;"> <u>T34N R55E</u> <u>S 31 S 32</u> <u>S 6 S 5</u> T33N </p> <p style="text-align: center;">1983</p> <p>Reset the original wooden post and set the steel fence post, 5½ ft. long, alongside the iron post.</p> <p>From this corner, a steel fence post, firmly set and exposed 4 ft. above ground, bears N. 41° 54' W., 8.84 chs. dist.</p>	
<p>40.80</p>	<p>N. 87° 23' W., bet. secs. 6 and 31.</p> <p>Over gently rolling land, through scattered sagebrush and native grass.</p> <p>Point for the N. ¼ sec. cor. of sec. 6, T. 33 N., R. 55 E., at proportionate distance; based on the Maxson resurvey in T. 33 N., R. 55 E., there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;"> <u>T34N R55E</u> <u>S 6</u> ¼ T33N </p> <p style="text-align: center;">1984</p> <p>Set a steel fence post, 5½ ft. long, alongside the iron post.</p>	
<p>40.87</p>	<p>Fence, bears N. and S.</p>	
<p>42.08</p>	<p>Point for the S. ¼ sec. cor. of sec. 31, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>NOT MONUMENTED</p>	
<p>76.50</p>	<p>Bullion Road, improved gravel, on curve from S. to NE.</p>	