

DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES,
T. 42 N., R. 60 E., MDM, NEVADA

CHAINS	
	From the cor. of secs. 5, 6, 7 and 8.
	N. 3° 27' E., bet. secs. 5 and 6.
	Over rolling land, through scattered sagebrush and native grass.
13.90	Trail road, bears NNE. and SSW.
16.70	Fence, bears NW. and SE.; enter bottom land.
39.98	Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.
	Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., flush with the surface of the ground, with brass cap mkd.
	T42N R60E
	S 6 $\frac{1}{4}$ S 5
	1987
	From this corner, the SE. corner of an old house at the Anderson Homestead, bears N. 12° 06' W., 14.14 chs. dist.
44.20	T Creek, 20 lks. wide, 5 ft. deep, course SE.
55.60	Fence, bears WNW. and ESE.
59.10	Trail road, bears NW. and SE.
79.77	The cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp.
	<hr/> GENERAL DESCRIPTION <hr/>
	The land within Township 42 North, Range 60 East, ranges from about 5800 to 7000 ft. above sea level, and is mostly rolling. The soil varies from silt loam along the Marys River and T Creek to sandy clay, gravelly and rocky on the higher elevations.
	The township is drained by T Creek and Marys River which flows south through the west tier of sections and Currant Creek which flows west through the center of the township.
	The Dixons Marys River Ranch buildings are located in section 19. Principal users of the area are cattlemen. Access into the township is provided by improved and unimproved roads.
	No mineral formations of consequence were noted during the survey. <hr/>