

DEPENDENT RESURVEY OF THE FIFTH STANDARD PARALLEL SOUTH,
THROUGH A PORTION OF RANGE 54 EAST,
T. 20 S., R. 54 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	DEPENDENT RESURVEY OF THE FIFTH STANDARD PARALLEL SOUTH, THROUGH A PORTION OF RANGE 54 EAST, T. 20 S., R. 54 E., MOUNT DIABLO MERIDIAN, NEVADA
	<p>Reestablishment of the Survey Executed by T. Binge, U.S. Deputy Surveyor in 1881.</p>
	<p>The standard cor. of secs. 32 and 33, on the S. bdy. of the Tp., monumented with an aluminum cap set flush at the intersection of Gamebird Road with Earp Ave., bears N., mkd. RL HAFEN RLS 4428. This cap correlates well with other existing original corners and is accepted as a careful and faithful perpetuation of the position of the original corner. This monument meets the standards set by the Bureau and was not remonumented.</p>
	<p>From this corner</p>
	<p>A stainless steel post, 28 ins. long, 2½ ins. diam., set 24 ins. in the ground, for a reference monument, bears N. 38° 07' E., 1.202 chs. dist., with brass cap mkd. SC T20S R54E S33 RM 79.3 FT 1990 and an arrow pointing to the true corner, with a steel fence post, 5½ ft. long, firmly set alongside.</p>
	<p>A stainless steel post, 28 ins. long, 2½ ins. diam., set 24 ins. in the ground, for a reference monument, bears N. 33° 39' W., 1.144 chs. dist., with brass cap mkd. SC T20S R54E S32 RM 75.5 FT 1990 and an arrow pointing to the true corner, with a steel fence post, 5½ ft. long, firmly set alongside.</p>
	<p>S. 89° 47.0' W., along the S. bdy. of sec. 32.</p>
	<p>Over level land, along Gamebird Road.</p>
37.584	<p>Intersect an aluminum cap, set flush with Gamebird Road, mkd. RL HAFEN RLS 4428.</p>
39.840	<p>The standard ¼ sec. cor. of sec. 32, on the S. bdy. of the Tp., monumented with an aluminum cap set flush at the intersection of Gamebird Road with Ironwood Ave., bears N., mkd. RL HAFEN RLS 4428. This cap correlates well with other existing original corners and is accepted as a careful and faithful perpetuation of the position of the original corner. This monument meets the standards set by the Bureau and was not remonumented.</p>