

DEPENDENT RESURVEY OF CERTAIN LINES OF
HOMESTEAD ENTRY SURVEY NO. 72

CHAINS	
0.20	Left bank, Owyhee River, bears irregularly N. and SSE.
0.461	Point for the original witness cor. to Cor. No. 5 of H.E.S. No. 72, on line 4-1 of M.S. No. 3986, Red Cross lode, hereinbefore described.
5.00	Left bank, Owyhee River, bears irregularly NW. and S.; thence across water course NW.
6.00	Right bank, Owyhee River, bears irregularly NW. and SE.
9.711	Point for Cor. No. 6 of H.E.S. No. 72, identical with Cor. No. 4 of M.S. No. 3986, Red Cross lode, hereinbefore described. Thence N. 84° 48' W., along line 4-3 of M.S. No. 3986, Red Cross lode.
0.80	Right bank, Owyhee River, bears irregularly NNW. and SSE.; thence across water course NNW.
1.70	Left bank, Owyhee River, bears irregularly NNW. and SSE.
9.060	Point for Cor. No. 7 of H.E.S. No. 72, identical with Cor. No. 3 of M.S. No. 3986, Red Cross lode, hereinbefore described. Thence S. 0° 22' E., along a portion of line 3-2 of M.S. No. 3986, Red Cross lode.
11.986	Cor. No. 8 of H.E.S. No. 72, hereinbefore described.
<p>DEPENDENT RESURVEY OF A PORTION OF EAST MOUNTAIN CITY TOWNSITE T 46 N., R. 53 E., MOUNT DIABLO MERIDIAN, NEVADA</p>	
<p>Reestablishment of the Survey Executed by Surveyor W.H. Settlemeyer, in 1940.</p>	
<p>From Cor. No. 4 of E.M.C.T. on line 1-15 of H.E.S. No. 39, monumented with a brass cap, 3 ins. diam., firmly set in a concrete block, 6 ins. square, showing 4 ins. above ground, mkd. E. MT. C.T. No. 4 1940.</p>	