SUBDIVISION OF SECTION 1, T. $23^{1}/_{2}$ N., R. 49 E., MOUNT DIABLO MERIDIAN, NEVADA

	T. 23/ ₂ N., R. 49 E., MOUNT DIABLO MEXIDIAN, NEVADA
CHAINS	Set an aluminum post, 28 ins. long, $2^1/_2$ ins. diam., 20 ins. in the ground to solid rock, over a plastic-encased magnet and in a collar of stone, 3 ft. base to top, with aluminum cap mkd.
	WP NW N———N S 1
	1998
	Continue over rolling, mountainous land.
20.032	The NW $^1/_{16}$ sec. cor. of sec. 1.
21.90	Fence, bears N. 41° E. and S. 41° W.
23.60	Wash, drains N.
40.064	The N $^1/_{16}$ sec. cor. of secs. 1 and 2.
	GENERAL DESCRIPTION
	The portion of the township that was resurveyed or subdivided is

The portion of the township that was resurveyed or subdivided is located at the southwestern end of Denay Valley and the northwestern end of the Roberts Mountains about 55 miles northwesterly of Eureka, Nevada. The elevation ranges from 6500 to 6700 feet above sea level. The terrain is rolling to mountainous. There are several sources of water with two of them being dammed up to form a reservoir in the northern part of section 1. The soil is predominately rocky clay with some sandy loam in the bottom of drainages with permanent sources of water. Vegetation is mostly sagebrush, native grasses and rabbitbrush with some cacti and Brigham tea. There are many juniper and pinon pine trees.

Access is provided by an improved gravel road crossing section 1 with several trail roads taking off from it. There is a fenced area in the northeast quarter of the northeast quarter of section 1 that encloses a well, pump and pump house. Also there is a single wood pole power line that crosses section 1 to serve leaching ponds and offices of Tonkin Springs Gold Mining Company in section 2. No mineral formations of any consequence were noted during the course of the resurvey.