

287

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,
T. 19 N., R. 20 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS

T19N	R20E
S 33	S 34
S 4	S 3
T18N	

1994

Reset the iron pipe alongside the stainless steel post.

CORRECTIVE DEPENDENT RESURVEY OF
A PORTION OF THE SUBDIVISIONAL LINES,
T. 19 N., R. 20 E., MOUNT DIABLO MERIDIAN, NEVADA

Reestablishment of a Portion of the Survey Executed by
E. H. Dyer, U. S. Deputy Surveyor, in 1863, and
Correction of a Portion of the Dependent Resurvey Executed by
Cadastral Engineer J. W. Hardison and Cadastral Surveyor
H. T. Brown, in 1956.

From the cor. of secs. 2, 3, 34 and 35, on the S. bdy. of the
Tp., hereinbefore described.

N. 0°47'20" W., bet. secs. 34 and 35.

Over rocky mountainous land, through scattered sagebrush and
native grass.

14.20 Trail road in ravine, bears NE. and SW.

19.981 Point for the S 1/16 sec. cor. of secs. 34 and 35.

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam.,
8 ins. in the ground to solid rock over a plastic encased magnet,
and in a mound of stone, 3 ft. base to top, with brass cap mkd.

S 1/16
S 34 S 35

1994

From this corner, the S 1/16 sec. cor. of secs. 34 and 35,
erroneously determined by Hardison and Brown in 1956, monumented
with an iron post, 2 1/2 ins. diam., firmly set in a mound of
stone, with brass cap mkd. as described in the field notes of the
dependent resurvey of the subdivisional lines of T. 19 N.,
R. 20 E., executed under Group No. 366, bears N. 44°03'00" E.,
2.261 chs. dist. Add the marks AM 1994 and bury the iron post in
the mound of stone.

26.30 Spur, slopes NW.

39.962 The 1/4 sec. cor. of secs. 34 and 35, monumented with an iron
post, 2 1/2 ins. diam., firmly set in a mound of stone, with
brass cap mkd. as described in the field notes of the dependent
resurvey of the subdivisional lines of T. 19 N., R. 20 E.,
executed under Group No. 366.
