

DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY,
T. 5 S., R. 40 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	<p>Deposit the original corner monument alongside and rebar inside of the stainless steel post.</p> <p>This control line was fully retraced and a careful search was made for intervening corners, none of which were found.</p> <hr/> <p style="text-align: center;">DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 5 S., R. 40 E., MOUNT DIABLO MERIDIAN, NEVADA</p> <hr/> <p style="text-align: center;">Reestablishment of a Portion of the Survey Executed by U.S. Deputy Surveyor N.L. Berdan in 1882 and a Portion of the Dependent Resurvey Executed by U.S. Cadastral Engineer J.C. Thoma and U.S. Transitman L.R. Mercer in 1918</p> <hr/> <p>From the cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the Tp., hereinbefore described.</p> <p>N. 1°07'30" E., bet. secs. 35 and 36.</p> <p>Over nearly level land.</p> <p>5.80 Nevada State Route No. 266, asphalt surface, 60 lks. wide, bears N. 65° E. and S. 65° W.</p> <p>25.00 Graveled road, 20 lks. wide, bears N. 70 1/4° W., and S. 70 1/4° E.</p> <p>40.005 The 1/4 sec. cor. of secs. 35 and 36, monumented with an iron post, 1 in. diam., firmly set, projecting 8 ins. above the ground, in a mound of stone, 3 1/2 ft. base, 8 ins. high, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> $\begin{array}{r} 1/4 \\ S35 \left \begin{array}{l} S36 \\ \hline 2LT \end{array} \right. \end{array}$ <p>1918</p> </div> <p>This cor. now refers to the 1/4 sec. cor. of sec. 36 only. Remark the brass cap as follows:</p> <div style="text-align: center; margin: 10px 0;"> $\begin{array}{r} 1/4 \\ \left \begin{array}{l} S36 \\ \hline 2LT \end{array} \right. \end{array}$ <p>1918 2005</p> </div> <p>A 5 ft. steel fence post is set alongside the iron post.</p> <hr/>
--------	---