

SUBDIVISION OF SECTION 2,
T. 4 S., R. 60 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	
	T4S R60E C 1/4 S 2 2012
	Insert rebar inside stainless steel post.
	From this cor., a standard Nevada Department of Transportation tablet, 24 ins. across, set in concrete, flush with the ground, mkd. STA B419+53.89 P.O.T. DIST. 160.37 ANGLE 90, bears S. 50°51'40" W., 18.021 chs. dist.
	From this same cor., a standard Nevada Department of Transportation tablet, set in concrete, 18 ins. across, flush with the ground, mkd. STA B419+53.89 P.O.T. DIST. 62.52 ANGLE 90, bears S. 59°28'40" W., 19.846 chs. dist.

	N. 0°20'00" W., beginning new measurement.
20.136	Point for the C-N 1/16 sec. cor. of sec. 2.
	Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, over a plastic-encased magnet, with brass cap mkd.
	C N 1/16 S 2 C
	2012
20.30	Fence, parallels Nevada State Route 318.
28.10	Nevada State Route 318, 50 lks. wide, bears N. 20° E. and S. 20° W.
35.90	Fence, parallels Nevada State Route 318.
40.352	The 1/4 sec. cor. of sec. 2, on the N. bdy. of the Tp.

	From the 1/4 sec. cor. of secs. 1 and 2.
	S. 89°48'10" W., on the E-W center line of sec. 2.
	Over farmland.
19.848	The C-E 1/16 sec. cor. of sec. 2, determined by Lenard D. Smith, Nevada Professional Land Surveyor No. 12751, in 2003, monumented with a rebar, 5/8 in. diam., firmly set, 10 ins. below the ground, with an aluminum cap, 2 ins. diam., mkd. L. Smith C E 1/16 PLS 12751, as recorded in Lincoln County, Nevada, Record of Survey, Plat Book B, Page 498, File No. 120449, with a "T" post alongside rebar. This is accepted as a careful and faithful determination of the position of the corner.