



United States Department of the Interior



BUREAU OF LAND MANAGEMENT

Nevada State Office
1340 Financial Boulevard
Reno, Nevada 89502-7147
<http://www.blm.gov/nv>

OCT 14 2016

In Reply Refer To:
9600 (NV-952) I
Group No. 959, Nevada

Memorandum

To: Cadastral Office Section Chief

From: Chief Cadastral Surveyor for Nevada *Michael O. Hammer*

Subject: Correction to official plat and field notes, Group 959,
T. 19 N., R. 62 E., Mount Diablo Meridian, Nevada

The cadastral staff discovered that the bearing between the 1/4 section corner of section 24 and the corner of sections 13 and 24, on the east boundary of the township, was erroneously reported as N. 0°08'10" W. on the plat and field notes accepted September 1, 2016.

The file for Group No. 959 contains the surveyor's preliminary data and the correct bearing between the corners is N. 0°08'10" E.

Therefore, you are hereby authorized to prepare an amended set of field notes and an amended plat returning the correct bearing on the north one-half mile between the 1/4 section corner of section 24 and the corner of sections 13 and 24, on the east boundary of T. 19 S., R. 62 E. The field note record and the plat data will contain a statement explaining the reason for the amendment to the official record.