

Chamiz

Meanders of Sect 12 Island sec 12
 I commenced at the special meander
 cor. on the south side of island bet
 East and West halves of sec 12
 Thence with meanders in sec 12
 N65°00W 6.50 chs
 N80°15E 6.00 " No special meander cor.
 N86°30E 4.80 "
 N81°15E 7.00 "
 N75°00E 4.50 "
 N87°30E 5.20 "
 S42°00W 5.00 "
 S58°45W 10.60 "
 N83°00W 3.10 "
 N69°16W 6.38 " To special meander cor.
 and place of beginning

From the special meander cor. on the
 north side of island the cor. of
 sec. 1, 6, 7, 12 bears N53°47E 48.70 chs
 in a rock wall
 a rock marked as described by notes of Sur. Gen's Office from south

- 20.89 From the cor. of sec 1, 6, 7, 12 bet sec 7 and 12
~~rock marked as described by notes of Sur. Gen's Office~~
 no trace of fractional cor found
 Left bank of Truckee River
- 24.59 no trace of fractional cor. found
 Right bank of Truckee River
- 41.04 no trace of 1/2 sec. cor.
- 80.99 Point for sec cor. falls in county road
 no trace of corner found

West bet sec 12 & 13,
 39.32 intersect subdivisional line bet E and W
 halves of sec 12. 82 ft. south of ^{1/4 sec. cor. previously described.} sec. cor.
 Land level, soil gravelly loam a
 part of which is under cultivation
 Irrigation is necessary
 The remainder of the island is
 covered with sage brush There
 are no trees within the
 meandered land
 The other improvements consist