

Fourth Standard Parallel North
 T. 21. N. R. 31. E. 411 D 711

Chains

- 40.00 Set a Post for $\frac{1}{4}$ Sec. Cor. deposit a charred stake raise mound of earth with pits as per instructions Var. $17^{\circ} 5'$ East
- 49.50 Leave tule for land not subject to overflow bearing S. E. and N. E.
- 80.00 Set a Post for Standard Corners Secs 35 and 36. deposit a charred stake raise mound of earth with pits as per instructions Land West $\frac{1}{2}$ Tule
 Subject to overflow the same as in preceding mile. East half mostly 1st rate alluvial Soil. Vegetation some grass with different kinds of weeds

East On the South Boundary of Sec. 36.
 Var $17^{\circ} 15'$ East

- 13.00 Leave dry for tule land subject to overflow bears N. and S.
- 24.50 Leave tule land unfit for cultivation for dry land bearing N. E. and S. W.
- 32.00 Leave dry land for tule land subject to overflow bearing N. E. & S.
- 40.00 Set a post for $\frac{1}{4}$ Sec Cor, deposit a charred stake raise a mound of earth with pits as per instructions Var $17^{\circ} 15'$ East
- 54.50 Leave tule land subject to overflow for dry land bearing N. & S.
- 62.50 Leave dry land for tule land subject to overflow bearing N. W. & S.
- 80.00 Set a post for Standard Cor to Townships 21. N. Ranges 31st and 32nd East, deposit a charred stake raise a mound of earth with pits as per instructions