

Special examination of Twp. 27 N., R. 34 E.

In the examination of the surveys of T. 27 N., R. 34 E. I found 24 corners out of 29 that I run lines to. The corners are in a good state of preservation, fairly well built up and in every case properly marked. The missing corners evidently have been destroyed by heavy rains or cloudbursts. Although exceptional rough and mountainous in the northern and eastern part of the township, I am convinced from the present condition of the lines examined that the whole was surveyed. I am of the opinion that a re-survey of the township is not required, but that the missing corners can be properly re-established by a restoration survey of that portion of the township in which the mineral lands in question, are located.

*Thos. A. Haigh.*  
*U.S. Surveyor.*

*Dec - 23 - 1917.*