

(7)

seven years ago to the Pennsylvania Hill Mining Company.

---

NOTE-

I retraced the North boundary of Town. 44, N. R. 52 E. from the N. W. Cor. which I found, but could not find any of the other corners.

The Cor. to Secs. 2 & 3 on Town line checked out for location and distance as per original field notes, but as was located on steep side of creek bank had evidently been carried away by snow slides.

As this corner is located fully 500 ft. below the claims embraced in this survey and in dense growth of cottonwood, I retraced the line to the N. 1/4 Cor. to Sec. 2. but could not find the original Cor. as it was located on steep side hill, which is covered with slide rock and shale and had been carried away undoubtedly by snow slides; I therefore re-established this Cor., by setting limestone rock 8 ins. x 12 ins. x 24 ins. (chiseled 1/4) 1 ft. in ground and raised mound of earth and rock North of it and dug two pits on line. This checks with original field notes for line and distance and correctly for tie to old blacksmith shop and summit of N. & S. ridge.

---

---

---