The courses were deflected from the true meridian as determined by direct solar observation.

The distances were measured with a 500 ft. steel tape.

----NOTE

The disagreements between these field notes and the location amended certificates are due to errors in the latter.

---REPORT

The N. $\frac{1}{4}$ Cor. Sec. 33, T.3 N., R. 42 E. M.D.M. to which connection is herein given consists of a stone 6x7x9 ins. above ground chiselled $\frac{1}{4}$ on South side and X on top.

Cor. No.1, Sur. No. 2400 General Miles lode, consists of a post 4 ins. square, showing $2\frac{1}{2}$ ft. above ground scribed 1-2400

Cors.Nos.4 and 5, Sur. No. 2477 Hillside and Anna lodes consist of posts 4 ins. square, showing $2\frac{1}{2}$ ft. above ground scribed 4-2477 and 5-2477 respectively.

Cor. No.6, Sur. No. 2521, Denver lode consists of a post 4 ins. square, showing $2\frac{1}{2}$ ft. above ground scribed 6-2521.

Cor. Nos. 3-5, Sur. No. 2276 Table Mountain No. 5 and Table Mountain lodes consists of a post 4 ins. square, showing 4 ft. above the ground scribed 3-5-2276.

The intersections with lines of conflicting surveys were found upon the ground as given in the foregoing field notes.

Unite

boun

know

and s

and:

the bo

E.

known

repres

direct

furnis

Y COMMISSIO

1728