

## Survey No. 3148.

## Instrument.

This survey was made with a Berger No. 4 Light Mountain Transit. The courses were deflected from the true meridian as determined by a direct solar observation.

The distances were measured with a 500 ft. steel tape.

## Report.

The Gov. to Secs. 26, 27, 34 and 35, T. 13 N. R. 24 E, Int. Diablo B. and W., is a quartzite stone 8 x 10 ins., 14 ins. above ground in mound of stones, marked with 2 notches on east edge and one notch on south edge. The 14 Gov. between Secs. 26 and 35 could not be found.

## Surv. No. 1990

Relief lode. - Govs. Nos. 2 and 3 are pine posts 4 ins. square, 2 1/2 ft. above ground in mounds of stone, scribed respectively by 2-1990 and 3-1990.

Francis Lode or mine lode. - Govs. Nos. 1 and 2 are pine posts 4 ins. square, 2 1/2 ft. above ground, scribed respectively 1-1990 and 2-2-1990.

Golden Gate lode. - Gov. No. 2 is identical with Gov. No. 2 of the Francis Lode or mine lode of same survey. Gov. No. 3 is a pine post 4 ins. square, 2 1/2 ft. above ground in mound of stones, scribed 3-1990.

## Errors.

I find line 2-3 Surv. No. 1990, Relief lode to be N. 24° 58' E. 1480.9 ft. instead of N. 24° 53' E. 1500 ft. as returned in that survey.

I find line 1-2 Surv. No. 1990 Francis Lode or mine lode to be S. 76° 25' E. 1512.5 ft. instead of S. 76° 30' E. 1500 ft. as