

as determined by direct solar observation.

The distances were measured with a 500 ft. steel tape

Note

The disagreements between these field notes and the location certificates are due to errors in the latter.

Report.

The W. $\frac{1}{2}$ Cor. Sec. 24, T. 2 S., R. 42 E.M.D.M. to which connection is herein given consists of a stone 7x12x9 ins. above ground chiselled $\frac{1}{2}$ on West face and X on top.

Cor. No. 6, Sur. No. 2343 Holland lode, consists of a post 4 ins. square, showing 2 $\frac{1}{2}$ ft. above ground in mound scribed 6-2343

Cor. No. 1, ^{Ann.} Sur. No. 2267 ~~Am.~~ Denver lode, consists of a post 4 ins. square, showing 2 $\frac{1}{2}$ ft above ground in mound scribed 1-2267 Am.

Cor. No. 1, Sur. No. 2268, Neglected lode, consists of a post 4 ins. square, showing 2 $\frac{1}{2}$ ft. above ground in mound scribed 1-2268.

Cor. No. 3, Sur. No. 3236 Bowen lode, consists of a post 4 ins. square, showing 2 $\frac{1}{2}$ ft. above ground in mound scribed 3-3236.

Cor. No. 1, Sur. No. 3236 Anna May lode, consists of a post 4 ins. square, showing 2 $\frac{1}{2}$ ft. above ground in mound scribed 1-3236.

Cor. No. 2, Sur. No. 2922 Desert Rose lode, consists of a post 4 ins. square, showing 2 $\frac{1}{2}$ ft. above ground in mound scribed 2-2922.

The intersecting lines of conflicting claims were found upon the ground as given in the foregoing field notes.

The intersections with section lines were calculated from the approved notes of the public land surveys.