

Survey N. 3836--continued.

REPORT.

The lode line of this claim was run directly upon the ground; the side and end lines also, all of the tie lines of this claim were run directly upon the ground.

The N.E. Cor of Sec. 25, T. 13 N., R. 24 E. of Mount Diablo Base and Meridian, is a granite stone 12 by 8 by 6 inches, set in mound of stone, chiseled with 2 notches on the S. and 4 notches on the N. faces.

The S.E. Cor. of Sec. 25, said section, is an eruptive stone 18 by 10 by 8 inches, set in mound of stones, chiseled with 1 notch on the S. and 5 notches on the N. faces.

After careful search the $\frac{1}{4}$ Sec. Cor. on the E. line of Sec. 25 could not be found.

Survey No. 3436, Moray. Moray No. 1 and Moray No. 3 lodes.

Corners Nos. 3 and 4 Moray lode are fir posts, corners Nos. 3 and 4, Moray No. 1 lode and corner No. 2, Moray No. 3 lode are redwood posts, all the corners are properly set and scribed with the ^{www} number of the corner and survey; I find all courses and distances to be correct as approved.

Survey No. 3736, Diamond No. 2 Lode.

All of the corners are fir posts, properly set and scribed with the number of the corner and survey. I find all courses and distances to be correct as approved.

The certificate of location of the Pioneer lode does not furnish the true courses and lengths of the lines of the claim in every particular, the same are properly given in these field notes.

Howard M. Hammond

U.S. Mineral Surveyor.