

Survey No. 3977--continued

Instrument.

This survey was made with a W. and L. E. Gurley Mountain Transit (no number), the courses were deflected from a true meridian established by me June 24, 1909, and verified from the lines of surveys Nos 3736 and 3836, Diamond Nos 1 and 2 lodes and the Pioneer lode respectively; the distances were measured with a 300 feet steel tape.

Report.

The lode line of each location of this claim was run directly upon the ground. All tie lines were run directly upon the ground.

The N. E. Cor. of Sec. 25, T. 13 N., R. 24 E. of Mount Diablo Base and Meridian, is a granite stone, 12 by 8 by 6 inches, set in mound of stones, chiseled with 2 notches on the S. and 4 notches on the N. faces.

The S. E. Cor. of the said section, is an eruptive stone 18 by 10 by 8 inches, set in mound of stones, chiseled with 1 notch on the S. and 5 notches on the N. faces.

After careful search the $\frac{1}{4}$ section Cor. on the East line of said section 25 could not be found.

The $\frac{1}{4}$ Sec. Cor on the N. boundary of section 25, is an igneous stone 12 by 6 by 4 inches, set in mound of stones chiseled with $\frac{1}{4}$ on the N. face.

Survey No. 3736, Diamond, Diamond No. 1 and Diamond No. 2 lodes. All corners are fir posts, properly set and scribed with the number of corner and survey, also with the first letter of the name of the claim.

Survey No. 3836, Pioneer lode, Cor. No. 1 is a redwood and Cor. No. 5 is a fir post, both are properly set and scribed with the first letter of the name of the claim, and with the number of the corner and survey.

I find all lines of Surveys Nos 3736 and 3836 as to the courses and distances to be correct as approved.

Note- The amended certificates of location of the Diamond No. 3, Diamond Fraction No. 1 and the certificate of locat