

## R E P O R T .

The lode line of this location was run directly upon the ground, and the corners were established by means of offsets from the lode line. All tie lines were run directly upon the ground.

The S. 1/4 Cor., Sec. 36, T. 46 N., R. 53 E., M. D. B. & M., is a granite stone chiseled with 1/4 on the South face, with a mound of earth alongside.

Silver Bell lode, unsurveyed:---All of the corners are cottonwood posts, 4 ins. square, set in mounds of earth and properly scribed.

The location certificate of Soft Snap lode is defective inasmuch as it does not give correct bearings of the lines; but I found all corners standing and properly marked.

The S. 1/4 Cor., Sec. 36, T. 46 N., R. 53 E., M. D. B. & M., was the nearest standing corner of the public survey that I was able to find after diligent search.

NOTE.---There were no permanent bearing objects available at any of the corners of this survey.