

4,

SURVEY No. 4182.

and a 50 ft. steel tapes.

.....

REPORT.

I found the N.W. Cor. of Section 4, T.30 N. R. 24 E. M.D.B & M. to be properly marked and witnessed as in field notes of survey of West boundary of said section by a stone, 9 x 24 ins. in a small mound of rocks.

I found no workings nor monuments of any kind upon this claim, except the workings placed thereon by the claimant, or his grantors.

I found corner No. 6, Survey No. 4126, Alfred Gypsum Placer, R.B. Henderson, Claimant, to be a pine post 4 ins. square, standing 3 ft. above ground in a mound of earth and scribed 6-4126-Alfred.

I found Corner No. 2, survey No. 3602, Selenite Placer, Nick Curnow et. als. claimants, and Corner No3 Survey No. 3951, Esperanza Placer, R.B. Henderson claimant, to be a pine post 4 ins. square, standing 3 1/2 ft. above ground in a mound of earth and scribed 2-3602-Selenite and 3-3951-Esp.

I found line 6-5, Survey No. 4126, Alfred Gypsum Placer, R.B. Henderson, Claimant, to be correct as approved. I found Corner No. 5, Survey No. 4126, Alfred Gypsum Placer, to be a juniper post 4 x 5 ins. standing 3 ft. above ground in a mound of earth and stone and scribed 5-4126-Alfred.

There are no ledges nor indications of mineral upon the ground embraced within the boundaries of this claim, except Gypsum.

..... *Thos. P. Moakley* .....