

## Survey No. 4223

## Report.

The lode line of each location of this claim was run directly upon the ground and the several corners established by means of offsets from the lode lines. All the tie lines were run directly upon the ground.

The  $\frac{1}{4}$  Sec. Cor. between Secs. 29 and 32 T. 3 S. R. 59 E. Mt. Diablo B. & M. is a Quartzite stone,  $9\frac{1}{2} \times 15 \times 9$  ins. above ground, chiselled  $\frac{1}{4}$  on North face, mound of stone North of corner.

Lot No. 39 Indian Chief lode (amd.)

As no corners were found standing on this claim, the conflict with same was determined through the connection returned in Sur. No. 4006 High Fly lode. This connection makes the tie from Cor. No. 1 Lot No. 39 Indian Chief lode (amd.) to the  $\frac{1}{4}$  Sec. Cor. N.  $3^{\circ}52'$  E. 707.4 Ft. instead of N.  $5^{\circ}15'$  E. 814. Ft.

Sur. No. 4006 Elephant, Wiko Bell and High Fly lobes.

All the corners were found as described in the official records, properly set and scribed with the number of the corner and survey and first letters of the names of lobes. I found all courses and distances to be correct as approved.

Note. - The disagreements between these field notes and the location notice of the Mohawk lode and the amended location notice of the Denver lode with regard to the courses of the boundary and lode lines are due to errors in the latter.