

No.6. A shaft which bears from Cor.No.1 Merry Xmas lode
 N 42° W 220 ft. 5x7 ft. 16 ft. deep.
 Value\$100.

---ooo0oooo0ooo---
 OTHER IMPROVEMENTS.

There are no other improvements.

---ooo0oooo0ooo---
 INSTRUMENT.

This survey was made with a C.L.Berger Mining Transit,
 No.7238.. The courses were deflected from the true
 meridian as determined by direct solar observations. The
 distances were measured with 100-ft. and 660 ft. steel
 tapes.

---ooo0oooo0ooo---
 REPORT.

The lode line of each location of this claim was run
 either directly upon the ground or with intermediate points
 and the several corners established by means of offsets.
 All tie lines were run either directly upon the ground or
 by traverses, run upon the ground and submitted in a
 separate report herewith.

The N.W.Cor.Sec.19, T 10 N., R 44 E., M.D.M. is a
 granite stone with three notches chiseled on the south
 side and three notches chiseled on the north side and a
 'X' chiseled upon the top to designate the exact point,
 6x12 ins. showing 12 ins. above the ground.

Sur.No.3618 Valley View and Mariposa lodes.

Cors.Nos.5 and 6, Valley View lode, and Cors.Nos.

5,6 and 1 Mariposa^{lode} are pine posts, 4 ins. square properly

set and scribed with the number of the survey and corner,

I find^u course³⁶¹⁸ of line 5-6 Valley View lode and line 5-6

and 6-1 Mariposa lodes to be correct as approved.

Sur.No.4369 Regal lode.

Cors.No.1,2 and 3 are pine posts, 4 ins. square,

properly set and scribed with the initial R, the number

of the corner and survey. Lines 1-2 and 2-3 are correct