

SURVEY NO. 4496.- Continued.

REPORT - Continued.

Line 3-4 N. $22^{\circ} 22'$ E. 1500 ft.

Line 4 - 1 N. $67^{\circ} 38'$ W.- 600 ft.

This survey makes the tie from Cor. 1 Sur. No. 41 Paymaster to N. $\frac{1}{4}$ Cor. of Sec. 24, T. 20 N., R. 18 E. M. D. M., N. $11^{\circ} 20'$ E.- 347.50 ft. instead of N. $7^{\circ} 45'$ E. 361. ft. as given in the original notes.

Also the tie from Cor. 1 to Cor. 4 Sur. No. 39A. Paymaster is S. $65^{\circ} 09'$ E.- 200.57 ft.

The N. $\frac{1}{4}$ Cor. of Sec. 24, T. 20 N., R. 18 E. M. D. M. is a small mound of rock without any marks on them to identify the Cor. but it has been recognized for years as the original position of the Cor.

The N. E. Cor. of Sec. 24, T. 20 N., R. 18 E., M. D. M. is a large rock in a mound of rock, chiseled 111 on south side and 111 on north side.

The bearing of the line from the N. $\frac{1}{4}$ Cor. to the N. E. Cor. is S. $89^{\circ} 52' 40''$ E.- 2728.21 ft.

The East $\frac{1}{4}$ Cor. of Sec. 24 T. 20 N., R. 18 E., M. D. M. is a large rock in a mound of rock chiseled 1/4.

The bearing of the line from the N. E. Cor. to the E. $\frac{1}{4}$ Cor. is S. $1^{\circ} 29'$ W. 2622.42 ft.

I spent two days running the line north from the N. E. Cor. of Sec. 24 and made diligent search for the E. $\frac{1}{4}$ Cor. and N. E. Cor. of Sec. 13, but could not find them and therefore have used a north course as given in the approved field notes in determining the intersection with line 3 - 4 Sunset lode.

Diligent search was made for the N. $\frac{1}{4}$ Cor. and the N. E. Cor. of Sec. 19, T. 20 N., R. 19 E., M. D. M., but I could not find them. I have therefore used the approved field notes in obtaining the intersection with line 2-3 Sunset lode of this survey.