

Mineral Survey No. 5063

FEET

No portion of or interest in these improvements has been credited theretofore as patent expenditures to any lode claims.

OTHER IMPROVEMENTS

The following drill holes were drilled prior to the location date of the CAL 312A lode and, there-fore, have no value, these drill holes are shown at the request of the claimant.

Drill Hole No. WC-218 bears N. 33°29' W., 532.3 ft. dist., from Cor. No. 1 of the CAL 312A lode, 5.25 ins. diam., 400 ft. deep.
No value.

Drill Hole No. WC-263 bears N. 61°39' W., 574.0 ft. dist., from Cor. No. 1 of the CAL 312A lode, 5.25 ins. diam., 600 ft. deep.
No value.

Drill Hole No. WC-275 bears N. 66°55' W., 982.9 ft. dist., from Cor. No. 1 of the CAL 312A lode, 5.25 ins. diam., 500 ft. deep.
No value.

Drill Hole No. WC-304 bears N. 72°25' W., 1252.0 ft. dist., from Cor. No. 1 of the CAL 312A lode, 5.25 ins. diam., 600 ft. deep.
No value.

 OTHER CORNER DESCRIPTIONS AND
SUPPLEMENTAL DATA

The cor. of Secs. 25, 26, 35, and 36, T. 41 N., R. 53 E., MDM, was found monumented with a rock, 9 ins. x 6 ins., 9 ins. above ground, marked with 1 notch on the south side and 1 notch on the east side, and a mound of stone 3 ft. south.

 FIELD ASSISTANTS

Name	Capacity
Boyd Syme	Chain/rodman
Brad Richins	Chain/rodman