

165

## Mineral Survey No. 5071

FEET

OTHER CORNER DESCRIPTIONS  
AND SUPPLEMENTAL DATA

The  $\frac{1}{4}$  sec. cor. of secs. 10 and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 8 ins. above the ground, with a 1986 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The C-N  $\frac{1}{16}$  sec. cor. of sec. 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 8 ins. above the ground, with a 1986 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The NE  $\frac{1}{16}$  sec. cor. of sec. 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 10 ins. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The N  $\frac{1}{16}$  sec. cor. of secs. 14 and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 6 ins. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The E  $\frac{1}{16}$  sec. cor. of secs. 10 and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., flush with the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The cor. of secs. 10, 11, 14, and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 6 ins. above the ground, with a 1984 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The S  $\frac{1}{16}$  sec. cor. of secs. 10 and 11, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 6 ins. above the ground, with a 1984 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The SW  $\frac{1}{16}$  sec. cor. of sec. 11, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 10 ins. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The W  $\frac{1}{16}$  sec. cor. of secs. 11 and 14, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 24 ins. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.

The  $\frac{1}{4}$  sec. cor. of secs. 14 and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 5 ins. above the ground, with a 1984 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.