

239 M

dug trench and pits. Planted stone on top $24 \times 13 \times 12$ inches: deeply marked on the North Face "O" on the South "N" on the East 239 M on the West 42 E.

Land mountain sides. Soil 2nd rate, good cattle range.

Bearings: to small mountain peak end of ridge $S 1^{\circ} 05' W$ distance $1\frac{1}{4}$ mile, to high peak $S 37^{\circ} 22' E$ distance 30 miles, to high mountain peak $N 40^{\circ} 32' E$ distance 5 miles.

start

Thence ascend crossing stony ridges and ravines putting down to South and then East to cañon at 25 chains cross dry creek ascend 28.50 chains to high bluff 38 chains cross bluff or benches, 42 chains cross bluff ascend 52 chains to summit of high mountain near middle of projecting bluff ridge. Put up a stone mound on this peak with flag for back sight as it is a very prominent object on line.

239 M
52 chs

Bearings: to high lone peak $N 48^{\circ} 49' W$ distance 40 miles, to small lone butte $S 85^{\circ} 40' W$ distance 21 miles, to center hot lake $S 39^{\circ} 20' W$ distance 6 miles, to high rough peak $S 19^{\circ} 10' E$ distance 7 miles, to spring on mountain side where observations were made $S 45^{\circ} 45' W$