

250 M
45 chs.

250 M 45 chs, on the West 42 I.

Bearings: to Knob on mountain N $50^{\circ} 20'$ E, distance 13 miles, to mountain peak N $41^{\circ} 28'$ W distance 9 miles, to high peak S $41^{\circ} 53'$ E, distance 25 miles, to near Knob (mountain Butte S $30^{\circ} 49'$ W distance $3/4$ mile.

From this point was obliged to offset to North $1/4$ mile to keep on table land in order that chaining might be possible as the line thence West runs along precipitous stone slide and into impassable cañons. Could not put in mile mounds.

At 252 M 25 chs return South $1/4$ mile to line at head of stony ravine, thence to mound at 252 M 40 chs. Built large stone mound, dug trench and pits.

Planted stone, $28 \times 20 \times 12$ inches: deeply marked on the north face "O" on the south

252 $\frac{1}{2}$ M

"N" on the East 252 M 40 chs on the West 42 I.

Bearings: to rocky mountain peak near East end range N $30^{\circ} 39'$ W distance 5 miles, to rocky small peak in cañon S $71^{\circ} 45'$ W distance $1\frac{1}{2}$ miles, to rocky end ridge S $14^{\circ} 34'$ W distance $3/4$ mile.

stop

Land worthless, rocky and cut by ravines. Built mound of earth of prescribed size, dug trench and pits. Planted stone, 16×12