

## North bdy. of frac. T.24 N.R.21 E.

## Chains.

July 27, 1911.

From the M.C. bet. secs. 3 and 4, 48.68 chs. N.  $0^{\circ} 02'$  W.  
of the cor. of secs. 3, 4, 9 and 10, I offset West  
22.60 chs. Thence, N.  $0^{\circ} 02'$  W., 31.32 chs. to bank  
of Pyramid Lake.

Set an iron post for M.C. bet. secs. 4 and 33 on N. bdy.  
of T. 24 N. R. 21 E., with brass cap stamped

M C in E. half  
T 25 N R 21 E S 33 in NW. quadrant  
T 24 N S 4 in SW. quadrant  
6 notches on N. and 6 on S. edges

Build a mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.  
Thence I run

West on a true line bet. secs. 4 and 33.

Ascending broken east slope.

5.60 Road, brs. N.  $20^{\circ}$  W. and S.  $20^{\circ}$  E.

17.40 Set an iron post for  $\frac{1}{4}$  sec. cor. bet. secs. 4 and 33,  
with brass cap stamped

$\frac{1}{4}$  S 33 in N. half  
S 4 in S. half

Build a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high, N. of cor.

57.40 Set an iron post for the cor. of secs. 4, 5, 32 and 33,  
with brass cap stamped

T 25 N S 33 in NE. quadrant  
R 21 E S 4 in SE. quadrant  
T 24 N S 5 in SW. quadrant  
S 32 in NW. quadrant  
4 notches on E. and 2 notches on W. edge

Build a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

Land, broken, - grazing.  
Soil, stony, 3rd rate.

From the cor, of secs. 4, 5, 32 and 33, I run

West on a true line bet. secs. 5 and 32.

Ascending steep NE. slope of mountain.

40.00 Set an iron post for  $\frac{1}{4}$  sec. cor. bet. secs. 5 and 32,  
with brass cap stamped

$\frac{1}{4}$  S 32 in N. half  
S 5 in S. half

Build a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high, N. of cor.