

Subdivision of frac. T. 23 N. R. 22 E.

Chains

GENERAL DESCRIPTION.

This township consists entirely of broken mountainous land. The soil is stony, 3rd rate. Several creeks drain into the lake carrying water from melting snow. Several of these sink before reaching the lake.

Several Indians have small ranches in this township. One Indian is located in the SE $\frac{1}{4}$ of the NW $\frac{1}{4}$ of sec. 24, having about 20 acres enclosed by fence, irrigating with water from Tom Anderson Canyon.

Another Indian has a cabin, and about 10 acres under cultivation, in the NE $\frac{1}{4}$ of sec. 25.

Rawhide Henry has a cabin, and about 10 acres under cultivation, in the SE $\frac{1}{4}$ of sec. 10, irrigating from Rodero Creek.

Mrs. Lydia Benoist has about 20 acres under cultivation in the W $\frac{1}{2}$ of the NW $\frac{1}{4}$ of Sec. 7. I did not survey these small tracts into 40 acre subdivisions since the small tracts are located in narrow canyons, and cannot be made to conform to legal subdivisions. Should it be decided to allot these lands to the several Indians claiming them, a metes and bounds survey will have to be made to describe them. Mrs. Lydia Benoist is one of the white persons on the Reservation, and holds no patent to her land.

In the early days some placer mining was done in Tom Anderson Canyon, but little mineral was obtained.

GUY P. HARRINGTON

U. S. Surveyor

List of Assistants:

Earl G. Harrington)	Instrumentman
Archie J. Strane		

Louis G. Hurst)	Chainmen
Henry W. Heine		
Alberto Axt		
Paul V. Rogers		

John W. Rodgers)	Moundsmen
Clifford Mc Laughlin		

Harry Grabow, Axemen

H. L. Heward)	Flagmen
Wm. Cort		