

- 2 -

Subdivision of frac. T. 24 N., R. 22 E.

Chains

From the M.C. bet. secs. 31 and 36, on W. bdy. of Tp.,

I run with meanders in sec. 31.

Over rolling land, along rocky shore of Pyramid Lake.

S. 63° 00' E. 9.20 chs.

N. 84° 00' E. 25.00 " At 21.50 chs. - Enter Mullen
Creek, from S. 30° W.

S. 83° 00' E. 17.20 "

S. 31° 45' E. 1.50 "

S. 15° 00' E. 29.85 "

S. 68° 00' E. 21.17 " To M.C. of secs. 31 and 32.

Land, rolling and grazing.

Soil, stony, 3rd rate.

Thence in sec. 32.

Over rolling land, along rocky shore.

S. 87° 00' E. 28.95 chs.,

S. 7° 45' E. 17.05 "

S. 20° 15' E. 18.78 " To M.C. bet. secs. 5 and 32, on
S. bdy. of Tp.

Land, rolling and grazing.

Soil, stony, 3rd rate.

July 19, 1910. At the M.C. bet. secs. 5 and 32, I set
off 20° 58' N. on the decl. arc, and at 12h 06m 01s p.m.
l.m.t., observe the sun on the meridian; the resulting
lat. is 39° 54', the proper lat.

GENERAL DESCRIPTION

This small fractional township consists of rolling land.
The soil is sandy and stony, 2nd and 3rd rate. The balance
of the township lies wholly in Pyramid Lake.

GUY P. HARRINGTON

U. S. Surveyor.

List of Assistants

Earl G. Harrington, Instrumentman

Alberto Axt, Chainman

Paul V. Rogers, Chainman

Clifford Mc Laughlin, Moundsman

H. L. Heward, Flagman