

## Subdivision of frac. T. 23 N. R. 23 E.

## Chains

Thence through sec. 28.

Over nearly level land, banks well defined.

N. 64° 25' E. 8.79 chs. To 1/16 M.C.  
 N. 62° 00' E. 3.50 "  
 N. 47° 30' E. 7.70 "  
 N. 22° 28' E. 14.09 " To 1/16 M.C.  
 N. 3° 15' W. 4.55 "  
 N. 13° 10' W. 15.94 " To M.C. bet. secs. 21 and 28.

Land, nearly level, - grazing.  
 Soil, sandy loam, 1st rate.

---

Thence through sec. 21.

Over nearly level land, banks well defined.

N. 34° 00' W. 9.40 chs.  
 N. 55° 35' W. 15.64 " To M.C. bet. secs. 20 and 21.

Land, nearly level, - grazing.  
 Soil, sandy loam, 1st rate.

---

## GENERAL DESCRIPTION.

This township consists of level, rolling and mountainous land. The soil ranges from a sandy loam, 1st rate, to a stony, 3rd rate. A small strip of land along the Truckee River is under irrigation. All portions of the township, except the extreme SW. portion, would be agricultural if irrigated.

The Indian Agency and school are situated in the SW $\frac{1}{4}$  of sec. 25. Practically all of the Indians of the reservation reside in this township.

Guy P. Harrington,  
 U. S. Surveyor.

## List of Assistants:

Earl G. Harrington	)	Instrumentmen
Archie J. Strane		
Alberto Art	)	Chainmen
Paul V. Rogers		
Louis G. Hurst		
E. W. Hoagland		
J. W. Rodgers	)	Moundsmen
Clifford Mc Laughlin		
William Cort	}	Flagmen
H. L. Heward		
Harry Grabow	)	Axemen
Geo. Brommers		