

Between Ranges 2542nd E
T₁₄ N

set a quartz stone
15x12x10 in. in mound
of stone as per instructions
for $\frac{1}{4}$ sec. cor.
no trees near for marking
ing

ascend

7150 Ravine bearing NE

So cor to secs 1, 6, 7, 12.

set a trap stone 18x6x12 in
in mound of stone as per
instructions for sec. cor.

no trees near for marking
cor on nearly level ground.

This mile or dry
country with some grass

North between Secs 1, 6

N, 6.30 E

2. Ravine bearing E