

T. 32 N. R. 44 E.

Field Notes of the Subdivision lines in
Township 32 North - Range 44 East
Mount Diablo Base and Meridian

Subdivision commenced August 21st, 1869
The South Eastern part of this township
being poor soil, alkalie mostly lilly and not
suitable for Cultivation, I begin at the
Corner to Sect. 13rd and 24 on the Eastern boundary
of the township and run thence
West, on a true line between Sect. 13rd and 24
Var. $17^{\circ} 45'$ East

40.00 Set a charred post in ground with pits as per
instructions for $\frac{1}{4}$ Sec Corner

80.00 Set a charred post in ground with pits as per
instructions for Cor. to Sect. 13rd - 14th - 23rd and 24th
Sand level - soil 2nd rate
Grease wood

Note - Land to the South and West rolling, alkalie
and unfit for Cultivation