

East, on a random line bet Sec^s. 3 and 10

Var. $16^{\circ}35'$ East

40.00 Set a post for temporary $\frac{1}{4}$ Sec. Cor.

80.35 Intersect N and E line $22^{\frac{1}{2}}$ N. of the Corner to Sec^s. 2 ~ 3 ~ 10 and 11

From which Corner I run

N $89^{\circ}51'$ W. on a true line between Sections 3 and 10

Var $16^{\circ}35'$ East

40.18 Set a charred post in mound with pits as per instructions for $\frac{1}{4}$ Sec. Cor.

80.35 The Corner to Sec^s. 3 ~ 4 ~ 9 and 10

Sand level ~ soil $2^{\frac{1}{2}}$ x 4

Grease wood

North, between Sections 3 and 4

Var. $16^{\circ}35'$ East

40.00 Set a charred post in mound with pits as per instructions for $\frac{1}{4}$ Sec. Corner

80.33 Intersect the 5^{th} Standard Parallel North at a point $8^{\frac{1}{2}}$ $50^{\frac{1}{2}}$ W. of the Standard Corner