

T 30 N ~ W 59 E

North, between Sections 4th and 5

Var 17° 10' East

5.30 Enter barley field, bears E and W

18.20 Leave field, bears E and W. enter meadow

40.00 Set a charred post in mound with pits as
per instructions for $\frac{1}{4}$ Sec. Cor.

79.90 Intersect the 6th Standard Parallel North
at a point 10^{ch} 75^{ch} W. of the Standard
Corner to Secs. 32nd and 33 of Township 31
North Range 59E. Where I set a charred
post in mound with pits as per instructions
for Closing Corner to Secs. 4 and 5
Land Level - soil 1st rate
Meadow and field

From the Cor. to Secs. 28 ~ 29 ~ 32nd and 33, I run
West, on a true line between Secs. 29 and 32

Var. 16° 45' East

40.00 Set a charred post in mound with pits
as per instructions for $\frac{1}{4}$ Sec. Cor.