

Subdivision Line in T. 30 N. R. 52 E. 2

+

North between Sec 33 & 34.

Va 17-00 E.

40.00

Set Cedar P. in M. of Earth with pits and charred stake as per instructions for $\frac{1}{4}$ Sec corner.

80.00

Set Cedar P. in M. of Earth with pits and charred stake as per instructions for cor to Sec 33. 34. 37 & 38

Land level and rolling Sage. Grassy. Soil 1st rate.

+

East on true Line between Sec 27 & 34

Va 17-00 E.

40.00

Set Cedar P. in M. of Earth with pits and charred stake as per instructions for $\frac{1}{4}$ Sec cor.

80.00

Set Cedar P. in M. of Earth