

Subdivision Line in T. 30 N. R. 52. E.

80.70 Intersected sixth Standard line  
9.04 chs East of Standard cor  
to Sec. 31 & 32. and  
Set Cedar P. in M. of Earth  
with pits and churred stake  
as per instructions for closing  
cor to Sec 3 & 6.

Land hilly, Sage, Grass.  
Soil poor.

I segregate the S. W.  $\frac{1}{4}$  of  
the S. E.  $\frac{1}{4}$  of Sec 5 as  
Swamp and overflowed  
land Dec 14<sup>th</sup> 1869.

General description

The Eastern portion of  
this Township is hilly and Mountainous  
and unfit for cultivation. It is well  
covered with grass which affords a fine  
range for stock. The Western portion is  
fine agricultural land covered with