

88 87A.

201

Subdivision lines S. 27 N. R. 52 E. ask
North between Sections

34. 35

Wa. 16-45 E

400v

Set slate stone 16x10x6 in
ground of stone as per instructions
for gr. rec. cor.

800v

Set cedar Pin in M. of earth with
pile and charred stake as per
instructions for cor. to rec.
26, 27, 34, 35.

Land hilly and barren.
Grass.

North between Sections

26. 27,

Wa. 16-45 E

400v

Traverse bears S E. N. W.

400v

Set cedar Pin in M. of earth with
pile and charred stake as
per instructions for gr. rec. cor.