

13

E Boundary T 34 N R 51 E 17 1/2 D 16

x North between SecD 7th Ma 12
Var 17° 30' East

4000 Set a charred post in mound with pits
as per instructions for 1/4 sec Cor

8000 set a charred post in mound with
pits as per instructions for Cor to
SecD 1-6-7th Ma 12

Land mountainous Soil 3rd rate
Sagebrush

x North between SecD 1st Ma 6
Var 17° 30' East

3500 a Spring flows SW

4000 Set a charred post in mound with
pits as per instructions for 1/4 sec Cor

8000 set a sand stone 36 V 10 V 10 as per
instructions for Cor to Townships 34 & 35
North Ranges 51st Ma 52 East

Land mountainous soil 3rd rate
Sagebrush.