

## T 35 North Range 52 East

99

North between Sec 5<sup>th</sup> and 6<sup>th</sup>  
Rar 17<sup>th</sup> 20<sup>th</sup> East

- 40.00 Set a Charcoal post in mound  
with pits as per instructions for  
1/4 sec Cor
- 45.00 Hot sulphur Spring 2 chs E of line
- 62.00 Enter meadow bears N E + S 10<sup>th</sup> N
- 81.15<sup>-</sup> Intersect 7<sup>th</sup> Standard Parallel  
North 11 chs + 60 lks E of Stand  
Cor to sec 31<sup>st</sup> and 32<sup>nd</sup> T 36 R 52 E  
where I set a charcoal post in  
mound with pits as per instructions  
for closing Cor to sec 5<sup>th</sup> and 6<sup>th</sup>  
Lana level soil mostly 1<sup>st</sup> rate  
Sagebrush bunch grass and  
some meadow.

March 10 1871