

N Boundary T16 N R 53 E
 Treas. poles of the Survey of the Exterior
 boundaries of T16 N R 53 E

start

October 21st 1871

Begin at the Cor to T16 N Range 52 & 53
 E in the 3rd Std Parallel North and
 run between said ranges

North between Sec 31 ^Q 31 36
 Var 16° 30' East

4000 set a charred post in mound with
 pits as per instructions for 1/4 sec Cor
 6220 a rock corner N.E. 1/4 sec
 8000 set a charred post in mound with
 pits as per instructions for cor to sec

25-30-31 ^Q 31 36

Land slopes N.E. soil 2nd rate

White sage

Note Base of mts bear N ^Q 31 36 to the West

North between Sec 25 ^Q 31 30
 Var 16° 30' E

4000 set a charred post in mound with
 pits as per instructions for 1/4 sec Cor