

T 15 N R 33 E

41

4011

Set a charred post in mound
with pits as per instructions for
1/4 Sec Cor

8022

The Cor to sec 4-5-8 ⁹mas 9
Land level rail 2 @ rate
White page.

North between Sec 4 + 5

Cor 16° 30' East

4000

Set a Charred Post in mound
with pits as per instructions for
1/4 Sec Cor

8030

Intersect Third Standard
Parallel North, at a point 5 ch
and 30 lks E of the Standard
Corner to Sec 32 + 33 T 16 N R 33 E
where I set a Charred Post
in mound with pits as per
instructions for Closing Cor