

18th 22
W boundary T38 N R 44 E

8000

put as per instructions for 1/4 sec cor
Set a charred post in mound
with pits as per instructions for
cor to sec 1-6-7th 12
Sandy level soil 2nd rate
Sagebrush 4th Greasewood.

North between sec 1st 6

Var 17° 30' East

4000

Set a charred post in mound with
pits as per instructions for 1/4 sec cor

4800

Dry Channel 10k under curve S. E

8000

Set a charred post in mound with
pits as per instructions for cor to
Townships 38th 39 North Ranges
43rd 44 East

Sandy rolling soil 2nd rate

Sagebrush 4th Greasewood.