

T. 10 N. R. 66 E. N. D. M.

80.08

The cor. to secs. 4, 5, 8, 9.

Smooth gravelly slope draining S.
White sage abundant.

stakes, pits

for 1/4 sec. cor.

North bet secs. 4 + 5.

Va. 16° E.

two pits +

cor. to secs

40.01

Set cedar post with charred stakes, pits +
earth mound pr. instructions for 1/4 sec. cor.

85.00

Intersect 2nd Standard Parallel N.

ing S.

22. chrs H. of Standard cor. bet. secs.

32 + 33. T. 11 N. R. 66 E. + set cedar

4 + 9.

E.

post with charred stakes, pits + earth
mound pr. instructions for closing
cor. bet secs. 4 + 5. T. 10 N. R. 66 E.Smooth gravelly slope draining S. -
White sage abundant.

cs. 3, 4.

Apr. 13. 1873-

North bet. secs. 31 + 32,

Va. 16° E.

D, pits +

40.00

Set cedar post with charred stakes, pits +
earth mound pr. instructions for 1/4 sec. cor.

1/4 sec. cor.