

132

165

T 35 N R 49 E.

Sage Brush and Punch Grass

North between Sections 1 and 2.

Var 17° 45' East

40.00 Set a charred post in mound with pits
as per instructions for $\frac{1}{2}$ Sec cor80.52 Intersect the $\frac{1}{2}$ Standard Parallel North
at a point 43rd 54th West of the Standard
Cor to Sec^s 35 and 36. T 36 N R 49 East
where I set a charred post in mound with
pits as per instructions for closing cor
to Sections 1 and 2.Land high rolling hills. Soil 2nd rate
Punch Grass and Sage Brush