

T 35 N R 49 E

North between Sections 2 and 3
Var. $17^{\circ} 45'$ East

40.00 Set a charred post in mound with pits
as per instructions for $\frac{1}{4}$ Sec cor

80.38 Intersect the 7^{th} Standard Parallel North
at a point 43^{ch} 54^{ch} West of Standard
cor to Secs 34 and 35 T 36 N R 49 E,
where I set a charred post in mound with
pits as per instructions for closing cor
to Sections 2 and 3.

Land rolling hills Soil 2nd rate

Bunch Grass and Sage Brush

North between Sections 33 and 34
Var. $17^{\circ} 45'$ East

40.00 Set a charred post in mound with pits
as per instructions for $\frac{1}{4}$ Sec cor

80.00 Set a charred post in mound with pits
as per instructions for cor to Sections