

1
T31 N R34 E. M. D. No. 2

Field Notes of the Survey of the Subdivision
Lines in T31 North R34 East
M. D. No.

Subdivision Begun Nov 12. 1873

The Eastern portion of this township being
steep rough mountains. Unfit for
cultivation, destitute of mineral and
timber. I began at the standard corner
to Section 34 W. 35, and run thence

North between Sections 34 W. 35
T31 N R34 E.

A Spring bears N 10° E. 8 chs distant
ascend.

- 9.00 Summit, N 65° S. descend.
- 20.00 Ravine, course N E. ascend
- 26.00 Summit of a ridge N 65° S. descend
- 39.00 Ravine, course N E. ascend